



Miltenyi Biotec

Miltenyi Biotec Inc.

6125 Cornerstone Court East
San Diego, CA 92121
USA

Phone: +1 530 888 8871
E-Mail: macs@miltenyibiotec.com
Web: www.miltenyibiotec.com

Responsible Department: Technical Support
Phone: +1 866 820 7385
E-Mail: technicalsupportUS@miltenyi.com

Print date: 5/15/2024

Product identifier: autoMACS Running Buffer – MACS Separation Buffer
Product code: 130-091-221

Statement

This reagent(s) does not contain any known hazardous chemicals or carcinogens at exposure limits defined as hazardous by 29 CFR 1910.1200(d). As a result, Safety Data Sheets are not required for this product [USA ref. OSHA, 29 CFR 1910.1200 and Appendix D; Canada ref. SOR/2015-17].